

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: )  
MASAHITO YOSHIDA, ET AL. ) : Examiner: Shih W. Hsieh  
Appl. No.: 10/765,399 ) : Group Art Unit: 2861  
Filed: January 28, 2004 ) : Confirmation No.: 2537  
For: PRINTING APPARATUS, PRINT HEAD )  
PERFORMANCE RECOVERY DEVICE AND )  
METHOD, AND PISTON PUMP ) :  
Patent No.: US 7,097,272 B2 )  
Issued: August 29, 2006 ) : March 10, 2008

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form (Form PTO-1050) is enclosed.

No fee is believed to be due with the filing of this Certificate of Correction. However, the Commissioner is authorized to charge any fee deemed necessary to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

---

Mark A. Williamson  
Attorney for Patentees  
Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

MAW:eyw

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 7,097,272 B2

DATED : August 29, 2006

INVENTOR(S) : YOSHIDA, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 15, "as" should read --as a--.

COLUMN 4:

Line 37, "constructions," should read --constructions--.

COLUMN 10:

Line 21, "is" should be deleted.

Line 66, "rollers **202**" should read --rollers **202**--.

COLUMN 13:

Line 28, "in knozzles" should read --ink nozzles--.

COLUMN 15:

Line 52, "CCW" should read --CCW--.

COLUMN 17:

Line 52, "grooves" should read --grooves--.

COLUMN 18:

Line 56, "operation" should read --operation--.

COLUMN 19:

Line 13, "operation" should read --operation--.

COLUMN 20:

Line 30, "mounted" should read --mounted--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,097,272 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 7,097,272 B2

DATED : August 29, 2006

INVENTOR(S) : YOSHIDA, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 21:**

Line 4, "A1.B1." should read --A1, B1--.

**COLUMN 22**

Line 32, "head" should read --head--.

Line 65, "head" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,097,272 B2

No. of add'l. copies  
@ 30¢ per page

